




CUT 40 HF



- ☑ Pilot Arc Start increases cutting capability and cutting speed, it also improves working life of torch and torch parts
- ☑ Extremely compact and regulator
- ☑ Built-in gas/air filter and regulator
- ☑ Plasma Central connector makes torch connection quicker and easier
- ☑ Generator friendly allows to work with diesel generators and avoid failures due to its voltage spikes
- ☑ Built-in Protection Circuit of over temperature and over voltage and over current for better reliability

Light Industrial

DC 1 Phase

Processes

- Air plasma cutting

Optional Accessories

- Earth cable and clamp
- HF Cutting Torch



Cutting Power Plasma System

www.crepow.com

CE

RoHS

RoHS

CE



CREPOW®

Welding & Cutting Technology

MODEL	CUT 40 HF
Power Supply Voltage(V)	1+220/230/240±10%
Frequency(HZ)	50/60
Rated Input Power(KW)	3.8
Rated Input Current(A)	33
NO Load Voltage(V)	450
Cutting Current Range(A)	20-40
Rated Duty Cycle(40 C 10min)	60% 40A
Max Cutting Thickness(mm)	18
Net Weight(KG)/(LB)	7 KG/15 LB
Dimensions(MM)/(Inch)	480*135*250/19*5*10
Protection Class	IP23
Insulation Class	H
Cooling	AF