



Brass Earth Clamp



Connecting Welding, Creating Value...
Welding & Cutting Technology

Contents

Brass Earth Clamp

300A Earth Clamp	1-3
400A Earth Clamp	3
500A Earth Clamp	4-8
600A Earth Clamp	9
800A Earth Clamp	10
1000A Earth Clamp	11-12
1200A Earth Clamp	13-14
1500A Earth Clamp	14-15
2000A Earth Clamp	16-17
2500A Earth Clamp	17-18
3000A Earth Clamp	18
4000A Earth Clamp	18

Brass Rotary Device for Earth clamp

500A Brass Rotary Device	19
1000A Brass Rotary Device	20
1500A Brass Rotary Device	21
2000A Brass Rotary Device	21



300A



Brass-0161

SPECIFICATIONS

Model	Brass-0161
Max. Current (A)	300
Max. Clamp Distance (mm)	45
Weight (g)	275



Brass-0162

SPECIFICATIONS


Model	Brass-0161
Max. Current (A)	300
Max. Clamp Distance (mm)	45
Weight (g)	275



Brass-0104

SPECIFICATIONS


Model	Brass-0161
Max. Current (A)	300
Max. Clamp Distance (mm)	45
Weight (g)	275



Brass-0146

SPECIFICATIONS

Model	Brass-0161
Max. Current (A)	300
Max. Clamp Distance (mm)	45
Weight (g)	275



Brass-0207

SPECIFICATIONS


Model	Brass-0161
Max. Current (A)	300
Max. Clamp Distance (mm)	45
Weight (g)	275



Brass-0208

SPECIFICATIONS

Model	Brass-0161
Max. Current (A)	300
Max. Clamp Distance (mm)	45
Weight (g)	275



Brass-0216

SPECIFICATIONS

Model	Brass-0216
Max. Current (A)	300
Max. Clamp Distance (mm)	48
Weight (g)	360




SPECIFICATIONS

Model	Brass-0161
Max. Current (A)	300
Max. Clamp Distance (mm)	45
Weight (g)	275



SPECIFICATIONS

Model	Brass-0161
Max. Current (A)	300
Max. Clamp Distance (mm)	45
Weight (g)	275



SPECIFICATIONS

Model	Brass-0161
Max. Current (A)	300
Max. Clamp Distance (mm)	45
Weight (g)	275

400A



SPECIFICATIONS

Model	Brass-0214
Max. Current (A)	400
Max. Clamp Distance (mm)	30
Weight (g)	230



500A



Brass-0117

SPECIFICATIONS

Model	Brass-0117
Max. Current (A)	500
Max. Clamp Distance (mm)	59
Weight (g)	600



Brass-0167

SPECIFICATIONS


Model	Brass-0167
Max. Current (A)	500
Max. Clamp Distance (mm)	59
Weight (g)	615



Brass-0168

SPECIFICATIONS


Model	Brass-0168
Max. Current (A)	500
Max. Clamp Distance (mm)	40
Weight (g)	644



Brass-0114

SPECIFICATIONS


Model	Brass-0114
Max. Current (A)	500
Max. Clamp Distance (mm)	66
Weight (g)	1060



Brass-1010

SPECIFICATIONS


Model	Brass-1010
Max. Current (A)	500
Max. Clamp Distance (mm)	66
Weight (g)	1042



Brass-1011

SPECIFICATIONS


Model	Brass-1011
Max. Current (A)	500
Max. Clamp Distance (mm)	45
Weight (g)	424



Brass-0170

SPECIFICATIONS


Model	Brass-0170
Max. Current (A)	500
Max. Clamp Distance (mm)	45.25
Weight (g)	417



Brass-0171

SPECIFICATIONS


Model	Brass-0171
Max. Current (A)	500
Max. Clamp Distance (mm)	58
Weight (g)	650



Brass-0105

SPECIFICATIONS


Model	Brass-0105
Max. Current (A)	500
Max. Clamp Distance (mm)	58
Weight (g)	706



Brass-0113

SPECIFICATIONS

Model	Brass-0113
Max. Current (A)	500
Max. Clamp Distance (mm)	58
Weight (g)	715



Brass-0225

SPECIFICATIONS






Model	Brass-0225
Max. Current (A)	500
Max. Clamp Distance (mm)	58
Weight (g)	720



Brass-0172

SPECIFICATIONS

Model	Brass-0172
Max. Current (A)	500
Max. Clamp Distance (mm)	35
Weight (g)	750



Model	Brass-0209
Max. Current (A)	500
Max. Clamp Distance (mm)	37
Weight (g)	1054

Model	Brass-0173
Max. Current (A)	500
Max. Clamp Distance (mm)	40
Weight (g)	552

Model	Brass-0101
Max. Current (A)	500
Max. Clamp Distance (mm)	66
Weight (g)	2015

Model	Brass-0175
Max. Current (A)	500
Max. Clamp Distance (mm)	88.5
Weight (g)	1103

Model	Brass-0176
Max. Current (A)	500
Max. Clamp Distance (mm)	61
Weight (g)	889



Brass-0107

SPECIFICATIONS

Model	Brass-0107
Max. Current (A)	500
Max. Clamp Distance (mm)	37
Weight (g)	664



Brass-0177

SPECIFICATIONS


Model	Brass-0177
Max. Current (A)	500
Max. Clamp Distance (mm)	37
Weight (g)	661



Brass-0103

SPECIFICATIONS

Model	Brass-0103
Max. Current (A)	500
Max. Clamp Distance (mm)	37
Weight (g)	619



Brass-0178

SPECIFICATIONS

Model	Brass-0178
Max. Current (A)	500
Max. Clamp Distance (mm)	37
Weight (g)	629



Brass-0197


SPECIFICATIONS

Model	Brass-0197
Max. Current (A)	500
Max. Clamp Distance (mm)	37
Weight (g)	640



600A-800A Earth Clamp

600A



Brass-0109

SPECIFICATIONS

Model	Brass-0109
Max. Current (A)	600
Max. Clamp Distance (mm)	40
Weight (g)	837



Brass-0102

SPECIFICATIONS

Model	Brass-0167
Max. Current (A)	600
Max. Clamp Distance (mm)	36
Weight (g)	780


800A



Brass-0227

SPECIFICATIONS

Model	Brass-0227
Max. Current (A)	800
Max. Clamp Distance (mm)	45
Weight (g)	693



Brass-0224

SPECIFICATIONS

Model	Brass-0224
Max. Current (A)	800
Max. Clamp Distance (mm)	63
Weight (g)	810



Brass-0179

SPECIFICATIONS

Model	Brass-0179
Max. Current (A)	800
Max. Clamp Distance (mm)	38
Weight (g)	1047




Brass-0174

SPECIFICATIONS

Model	Brass-0174
Max. Current (A)	800
Max. Clamp Distance (mm)	38
Weight (g)	2000




1000A




SPECIFICATIONS

Model	Brass-0180
Max. Current (A)	1000
Max. Clamp Distance (mm)	70
Weight (g)	657




SPECIFICATIONS

Model	Brass-0181
Max. Current (A)	1000
Max. Clamp Distance (mm)	65
Weight (g)	1247




SPECIFICATIONS

Model	Brass-0215
Max. Current (A)	1000
Max. Clamp Distance (mm)	63
Weight (g)	1200




SPECIFICATIONS

Model	Brass-0182
Max. Current (A)	1000
Max. Clamp Distance (mm)	66
Weight (g)	3000




SPECIFICATIONS

Model	Brass-0229
Max. Current (A)	1000
Max. Clamp Distance (mm)	63
Weight (g)	2260



SPECIFICATIONS

Model	Brass-0200
Max. Current (A)	1000
Max. Clamp Distance (mm)	115
Weight (g)	4250




SPECIFICATIONS

Model	Brass-0176
Max. Current (A)	1000
Max. Clamp Distance (mm)	140
Weight (g)	6317

1200A-1500A Earth Clamp




1200A



Brass-0184

SPECIFICATIONS


Model	Brass-0184
Max. Current (A)	1200
Max. Clamp Distance (mm)	56
Weight (g)	1428



Brass-0183

SPECIFICATIONS


Model	Brass-0183
Max. Current (A)	1200
Max. Clamp Distance (mm)	56
Weight (g)	2250



Brass-0220

SPECIFICATIONS

Model	Brass-0220
Max. Current (A)	1200
Max. Clamp Distance (mm)	54
Weight (g)	1200




Brass-0221

SPECIFICATIONS

Model	Brass-0221
Max. Current (A)	1200
Max. Clamp Distance (mm)	54
Weight (g)	2105


1500A



Brass-0185

SPECIFICATIONS


Model	Brass-0185
Max. Current (A)	1500
Max. Clamp Distance (mm)	140
Weight (g)	4450




Brass-0186

SPECIFICATIONS


Model	Brass-0186
Max. Current (A)	1500
Max. Clamp Distance (mm)	115
Weight (g)	2300




Brass-0187



Brass-0188



Brass-0212



Brass-0213



Brass-0217

SPECIFICATIONS

Model	Brass-0187
Max. Current (A)	1500
Max. Clamp Distance (mm)	140
Weight (g)	8150

SPECIFICATIONS

Model	Brass-0188
Max. Current (A)	1500
Max. Clamp Distance (mm)	115
Weight (g)	6050

SPECIFICATIONS


Model	Brass-0212
Max. Current (A)	1500
Max. Clamp Distance (mm)	135
Weight (g)	5000

SPECIFICATIONS


Model	Brass-0213
Max. Current (A)	1500
Max. Clamp Distance (mm)	140
Weight (g)	8000

SPECIFICATIONS

Model	Brass-0217
Max. Current (A)	1500
Max. Clamp Distance (mm)	/
Weight (g)	/




2000A



Brass-0199

SPECIFICATIONS


Model	Brass-0199
Max. Current (A)	2000
Max. Clamp Distance (mm)	140
Weight (g)	10800



Brass-0211

SPECIFICATIONS


Model	Brass-0211
Max. Current (A)	2000
Max. Clamp Distance (mm)	115
Weight (g)	8650




Model	Brass-0218
Max. Current (A)	2000
Max. Clamp Distance (mm)	/
Weight (g)	/

Brass-0189


Model	Brass-0189
Max. Current (A)	2500
Max. Clamp Distance (mm)	77
Weight (g)	7300



Model	Brass-0190
Max. Current (A)	2500
Max. Clamp Distance (mm)	110
Weight (g)	10300



Model	Brass-0202
Max. Current (A)	2500
Max. Clamp Distance (mm)	110
Weight (g)	10600




Brass-0222

SPECIFICATIONS

Model	Brass-0222
Max. Current (A)	2500
Max. Clamp Distance (mm)	/
Weight (g)	8700


3000A



Brass-0219

SPECIFICATIONS

Model	Brass-0219
Max. Current (A)	3000
Max. Clamp Distance (mm)	/
Weight (g)	/




Brass-0228

SPECIFICATIONS

Model	Brass-0228
Max. Current (A)	3000
Max. Clamp Distance (mm)	110
Weight (kg)	11.3

4000A



Brass-0222

SPECIFICATIONS

Model	Brass-0223
Max. Current (A)	4000
Max. Clamp Distance (mm)	/
Weight (g)	18300



500A Brass Rotary Device



Brass Connector-0201

SPECIFICATIONS

Model	Brass Connector-0201
Max. Current (A)	500
Size (mm)	97
Weight (g)	443



Brass Connector-0191

SPECIFICATIONS


Model	Brass Connector-0191
Max. Current (A)	500
Size (mm)	140
Weight (g)	923

1000A Brass Rotary Device



SPECIFICATIONS

Model	Brass Connector-0192
Max. Current (A)	1000
Size (mm)	110
Weight (g)	950



Brass Connector-0193

SPECIFICATIONS

Model	Brass Connector-0193
Max. Current (A)	1000
Size (mm)	110*120
Weight (g)	1830



Brass Connector-0194

SPECIFICATIONS

Model	Brass Connector-0194
Max. Current (A)	1000
Size (mm)	103*120
Weight (g)	1829



Brass Connector-0195

SPECIFICATIONS

Model	Brass Connector-0195
Max. Current (A)	1000
Size (mm)	115*120
Weight (g)	1889

1500A Brass Rotary Device



Brass Connector-0153

SPECIFICATIONS

Model	Brass Connector-0153
Max. Current (A)	1500
Size (mm)	140*170
Weight (g)	4000

2000A Brass Rotary Device



Brass Connector-0196

SPECIFICATIONS


Model	Brass Connector-0196
Max. Current (A)	2000
Size (mm)	165
Weight (g)	6500



Brass Connector-0226

SPECIFICATIONS

Model	Brass Connector-0226
Max. Current (A)	2000
Size (mm)	133
Weight (g)	4250



✉ sales@crepow.com

🌐 www.crepow.com