

FEATURES


- Digital meter is easy to read display current and air pressure.
- Built-in air filter and regulator
- Plasma Central connector makes torch connection quicker and easier
- Pilot Arc Start increases cutting capability and cutting speed, it also improves working life of torch and torch parts
- 2T/4T makes job more easier and comfortable
- Postflow cooling circuitry extends life of the consumable and torch by cooling them with postflow air after trigger is released
- Built-in Protection Circuit of over temperature and over voltage and over current for better reliability



SPECIFICATIONS

Model	Input power supply	Effective input Amps	Rated input power (KW)	Rated output at 40°C	No-load Volts	Max.Cutting thickness	Dimensions	Net weight	Protection class
CUT 40 HF	1ph 220V±15% 50/60Hz	14 A	7.5 Kw	40A@25%	310	15mm	L:415mm(16.3in.) W:155mm(6.1in.) H:315mm(12.4in.)	7.8Kg(17.1lb.)	IP 21S

CONTROL PANEL



1. Cutting current knob: It is used to adjust current.
2. Power indicator: When the machine is connected to the power supply, the indicator lights on.
3. Alarm indicator: When over-heat or over-current, the indicator lights on.

OPTIONAL ACCESSORY



PLASMA Torch-CB50



Earth Lead
(6mm²+300A earth clamp)



Gas Hose